

Environmental Protection (Darling Range Bauxite Mining Proposals) Exemption Order 2023

Alcoa Monthly Report
Clause 10

November 2025



Monthly Reporting Dashboard – Page 1

Section 10 Monitoring Potential Drainage Incidents


Turbidity Data		Drainage Incidents	
Site	No. Active Monitors ¹	Site	No. Events (Nov-25) ²
Huntly	35	Huntly	0
Willowdale	4	Willowdale	0
Total	39	Total	0

¹ Refers only to monitors located in areas covered by the Exemption Order.

² Potential Events - Currently being investigated in accordance with section 6(2) of the Exemption Order to determine whether any of the events were mining related.

Section 2 – Clause 10 2(c) (i) Production and Exploration Summary

Production (HUN and WDL)	Month (Nov-25)	YTD (CY)	Limit	Status
Production Tonnes Huntly	1.5	15.4		
Production Tonnes Willowdale	0.9	10.3		
Total Bauxite Production Tonnes	2.4	25.7	38 MT	
Exploration	Month (Nov-25)	YTD (CY)	Limit	Status
Total Exploration Holes	7,714	64,036	105,000	



Section 3 Clause 10 2(c) (i) and Clause 10 2(c) (iii) Activities Summary and Forecast

Area	November 2025			December 2025			January 2026		
	*Cleared	Stabilised	Seeded	*Clearing	Stabilised	Seeded	*Clearing	Stabilised	Seeded
Huntly									
Total HUN Mine Disturbance Footprint (ha)	18.8	0	0	25.4	136.8	65.5	32.3	108	81
Total WDL mine disturbance footprint (ha)	0	0	0	0	0	10	0	0	61.7

* Clearing only considers completed hectares

Definitions

- Cleared – disturbance to native vegetation and other flora
- Stabilised – in relation to an area that has been disturbed, means carry out landscaping, ripping and other appropriate operations to prevent erosion of sediment, promote infiltration and manage surface water runoff
- Seeded – landform established and seeding complete

Monthly Reporting Dashboard – Page 2

Section 4 – Clause 2(c) (ii)

Activities Ceased during the Period for Huntly

Area	November 2025		
	Haul Roads ^(a)	Infrastructure ^(b)	Mining
Within 1km Reservoir (ha)	0	0	0
Serpentine Pipehead Dam Catchment (ha)	0	0	0
Within RPZ and >16% average slope (ha)	0	0	0
Within 10m of BC nesting/significant trees (ha)	0	0	0

Definitions

(a) Haul roads includes road infrastructure

(b) Infrastructure Includes drainage control, mining and monitoring infrastructure



Maps for Huntly

No cessation activities to report this month

Cessation of mining activities in the above-mentioned areas is not applicable to the Willowdale mine


Maps for Willowdale


Appendix A – Monitoring Results



Appendix A – Monitoring Results

Exploration





Huntly


01-11-2025 to 30-11-2025

- Clearing
- Area Open
- Mine Disturbance Footprint
- Mt Solus 1.5km Buffer
- Serpentine Pipehead Dam Catchment
- Within 1km of Reservoir
- Reservoir Protection Zones (RPZ)
- Slope >16% (Landgate Derived)

0 2.5 5 10
Kilometres

 Alcoa

Date Exported: 2025-12-03



Willowdale

01-11-2025 to 30-11-2025


0 1 2 4
Kilometres

- Clearing
- Area Open
- Mine Disturbance Footprint

- Within 1km of Reservoir
- Reservoir Protection Zones (RPZ)
- Slope >16% (Landgate Derived)



Date Exported: 2025-12-03



• Exploration Drill Holes
Exploration Disturbance Footprint

Mine Footprint
Within 1km of Reservoir
Reservoir Protection Zones (RPZ)

Exploration
01-11-2025 to 30-11-2025

0 1.25 2.5 5
Kilometres

Alcoa

Date Exported: 2025-12-03